Message Text

UNCLASSIFIED

PAGE 01 LONDON 03585 080029Z

15

ACTION OES-05

INFO OCT-01 EUR-12 ISO-00 ERDA-07 EB-07 FEA-01 ACDA-10

CIAE-00 INR-07 IO-10 L-02 NSAE-00 NSC-05 COME-00 /067 W

----- 079611

R 071951Z MAR 75

FM AMEMBASSY LONDON

TO SECSTATE WASHDC 9070

UNCLAS LONDON 03585

FOR OES FROM HULM

PASS DE FLEUR, ERDA

E.O. 11652: N/A TAGS: TECH

IAGS. ILCII

SUBJ: CRACKS IN PIPING OF BOILING WATER REACTORS

HAVE RECEIVED FOLLOWING COMMENTS ON MECHANISM OF CRACKING OF STAINLESS STEEL IN BWR APPLICATIONS FROM DR. W. MARSHALL, DIRECTOR OF ATOMIC ENERGY RESEARCH ESTABLISHMENT, HARWELL:

QUOTE. THANK YOU FOR YOUR LETTER OF 3RD FEBRUARY AND THE ENCLOSURES ON THE RECENT CRACKS FOUND IN BWR COM-PONENTS. CRACKING OF STAINLESS STEEL UNDER BWR CONDITIONS HAS BEEN REPORTED FULLY IN THE SCIENTIFIC LITERATURE BY VARIOUS AMERICAN WORKERS OVER THE LAST 1-2 YEARS. THE CRACKING GENERALLY FOLLOWS AN INTER-GRANULAR PATH BETWEEN THE METAL GRAINS OF THE STEEL. VARIOUS FACTORS ENHANCE FAILURE, IN PARTICULAR A HIGH STRESS NEAR THE YIELD POINT OF THE STEEL SUCH AS MIGHT OCCUR AT NOZZLES, HIGH INTERNAL STRESSES PRODUCED IN FABRICATION, SENSITIZATION OF THE STEEL WITH THE FORMATION OF CHROMIUM CARBIDE PARTICLES AT METAL GRAIN BOUNDARIES, AND FREE OXYGEN TOGETHER WITH OTHER CON-TAMINANTS SUCH AS CHLORIDE IONS IN THE ENVIRONMENT. THESE FACTORS INTERACT ON ONE ANOTHER TO GOVERN CRACK PROPAGATION RATES AND THRESHOLD CONDITIONS FOR CRACKING. UNCLASSIFIED

UNCLASSIFIED

PAGE 02 LONDON 03585 080029Z

THE WIDESPREAD USE OF 304 STEEL IN WHICH THE CARBON

IS FREE TO SENSITIZE THE STEEL DURING VARIOUS HEAT TREATMENT PROCEDURES INCREASES SIGNIFICANTLY THE PROBABILITY OF CRACKING IN BWRS. WELDS ARE PARTICULARLY SUSCEPTIBLE AS WELDING PRODUCES RESIDUAL STRESSES AND HEAT TREATMENTS OF THE NEIGHBORING METAL WHICH LEADS TO SENSITIZATION. THE 316 STEEL CAN ALSO BE READILY SENSITIZED ALTHOUGH IT IS NOT QUITE SO SUSCEPTIBLE DUE TO THE REPLACEMENT OF SOME CHROMIUM IN THE CARBIDE PHASE BY MOLYBDENUM. THE PUBLISHED LITERA-TURE ON CRACKING REFERS PRIMARILY TO THE 304 STEEL DUE TO THE MORE WIDESPREAD USE OF THIS STEEL. THE PROBLEM COULD BE CONSIDERABLY ALLEVIATED BY THE USE OF STABILIZED STEELS IN WHICH THE CARBON IS BOUND TO TITANIUM OR NIOBIUM IN THE FORM OF THEIR CARBIDES ALTHOUGH THIS MOVE MIGHT NOT ELIMINATE ALL CRACKING. GENERAL ELECTRIC APPEAR TO BE RESISTING A CHANGE TO STABILIZED STEELS FOR REASONS WHICH ARE NOT CLEAR. THIS TYPE OF CRACKING IS, OF COURSE, NOT OBTAINED IN PWRS DUE TO THE ABSENCE OF FREE OXYGEN IN THE WATER OF THESE REACTORS. IF THE RECENT CRACKS PROVE TO BE TRANSGRANULAR. THEY COULD BE TYPICAL OF STRESS CORROSION PROCESSES ARISING IN A WIDE RANGE OF NON-NUCLEAR SITUATIONS DUE TO THE PRESENCE OF APPRECIABLE LEVELS OF CHLORIDE IONS AS WELL AS OF OXYGEN IN THE ENVIRONMENT. ALTERNATIVELY, FATIGUE PROCESSES MIGHT BE SIGNIFICANT AS IN THE CORROSION FATIGUE OF PRESSURE VESSEL STEELS. IT IS UNLIKELY WE CAN OFFER ANY INFORMATION OVER AND WHILST THE FAILURES APPEAR TO FALL WITHIN THE EXPERIENCE SUMMARIZED ABOVE, THE SUBJECT OF CORROSION IS SO DIVERSE WITH NEW FAILURE MECHANISMS ARISING AT REGULAR INTERVALS, THAT DEPARTURES FROM THE EXPECTED BEHAVIOR CANNOT BE DISCOUNTED. SUCH DEPARTURE WOULD NATURALLY BE OF CONSIDERABLE INTEREST TO US IN THE UK. PARTICULARLY IF THERE IS A MAJOR TRANSGRANULAR ELEMENT IN THE CRACKING. COULD I THEREFORE PLEASE ASK YOU TO INFORM US IF ANY SUCH DEVELOPMENTS ARISE IN THE INVESTIGATIONS ON THESE

PLEASE NOTE DR. MARSHALL'S SPECIAL INTEREST IN THE SUBJECT AND DESIRE FOR ANY AVAILABLE BASIC INFORMATION OBTAINED FROM INVESTIGATION OF BWR PIPING FAILURES. UNCLASSIFIED

UNCLASSIFIED

FAILURES. UNQUOTE.

PAGE 03 LONDON 03585 080029Z

RICHARDSON

UNCLASSIFIED

	Margaret F. Grareiu Declassifieu/Neleaseu 03 Department of State	E EO Systematic Neview 03 JOE 2000
NNN		

Message Attributes

Automatic Decaptioning: X Capture Date: 01 JAN 1994 Channel Indicators: n/a

Current Classification: UNCLASSIFIED Concepts: NUCLEAR REACTORS

Control Number: n/a Copy: SINGLE Draft Date: 07 MAR 1975 Decaption Date: 01 JAN 1960 Decaption Note: Disposition Action: n/a Disposition Approved on Date: Disposition Authority: n/a Disposition Case Number: n/a

Disposition Camment:
Disposition Date: 01 JAN 1960
Disposition Event:
Disposition History: n/a

Disposition Reason: Disposition Remarks:

Document Number: 1975LONDON03585 Document Source: CORE Document Unique ID: 00

Drafter: n/a Enclosure: n/a Executive Order: N/A Errors: N/A

Film Number: D750081-0835 From: LONDON

Handling Restrictions: n/a

Image Path:

Legacy Key: link1975/newtext/t19750372/aaaacneh.tel Line Count: 109 Locator: TEXT ON-LINE, ON MICROFILM

Office: ACTION OES Original Classification: UNCLASSIFIED Original Handling Restrictions: n/a Original Previous Classification: n/a Original Previous Handling Restrictions: n/a

Page Count: 2

Previous Channel Indicators: n/a
Previous Classification: n/a Previous Handling Restrictions: n/a Reference: n/a Review Action: RELEASED, APPROVED Review Authority: CollinP0

Review Comment: n/a Review Content Flags: Review Date: 29 MAY 2003

Review Event:

Review Exemptions: n/a
Review History: RELEASED <29 MAY 2003 by RuthemTJ>; APPROVED <26 FEB 2004 by CollinP0>

Review Markings:

Margaret P. Grafeld Declassified/Released US Department of State EO Systematic Review 05 JÚL 2006

Review Media Identifier: Review Referrals: n/a Review Release Date: n/a Review Release Event: n/a **Review Transfer Date:** Review Withdrawn Fields: n/a

Secure: OPEN Status: NATIVE

Subject: CRACKS IN PIPING OF BOILING WATER REACTORS HAVE RECEIVED FOLLOWING COMMENTS ON MECHANISM OF CRACKING

TAGS: TECH To: STATE

Markings: Margaret P. Grafeld Declassified/Released US Department of State EO Systematic Review 05 JUL 2006